

Texturing Result of Aluminum Alloys (Honda 390 Grain)



**Texturing Result was successful for each AL Alloy.
Repair Results varied by each Alloy. (See Samples)**