


Tool Shop and Honda Verified



Porosity on 5000 series rod was worse than 2000 series and 4000 series performing the best